



CoverSeal™ PLUS

Fast Drying Universal Mounting Medium

REF #CS120 4oz

LOT



For In Vitro Diagnostics Use

59°F (15°C)  86°F (30°C)



4300 Emperor Blvd - 400 Durham, NC 27703
Tel: 1-877-846-5393 Fax: 1-877-817-1716
www.cancerdiagnostics.com

Made in USA

Date Received: _____ Date Opened: _____

CoverSeal Plus™ is a mounting medium which enables (non-paraffin[®]) slide preparations to be simultaneously cleared and coverslipped in one easy step. This unique product eliminates the need to use xylene or xylene substitutes as a clearing agent. When using CoverSeal Plus™, simply do away with the final step of clearing and coverslip directly from 99% isopropyl alcohol. *Optimal medium for frozen sections and cytology applications.



DANGER HAZARD STATEMENTS

Highly flammable liquid and vapor. May be fatal if swallowed and enters airways. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. May cause respiratory irritation. May cause drowsiness or dizziness. Suspected of damaging fertility or the unborn child. May cause damage to organs through prolonged or repeated exposure.

PRECAUTIONARY STATEMENTS - PREVENTION

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe dust/fume/gas/mist/vapors. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves/protective clothing/eye protection/face protection.

PRECAUTIONARY STATEMENTS - RESPONSE

IF EXPOSED OR CONCERNED: call a doctor/get medical attention.

IF ON SKIN: Wash with plenty of water/shower. Take off all contaminated clothing and wash it before reuse. If skin irritation or rash occurs or persists: Get medical advice/attention.

IF INHALED: Remove person to fresh air and keep comfortable for breathing.

IF SWALLOWED: Immediately call a POISON CENTER/doctor/physician. Specific treatment (see first aid section on SDS). Do NOT induce vomiting.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

IN CASE OF FIRE: Use CO₂, dry chemical, or foam for extinction.

STORAGE & DISPOSAL

Keep container tightly closed. Store locked up in a well ventilated place at room temperature. Keep cool. Dispose of contents/container to an approved waste disposal plant.

NOTICE: Read Safety Data Sheet for additional information.

EMERGENCY CONTACT: Chemtec 1-800-424-9300



CoverSeal™ PLUS

Fast Drying Universal Mounting Medium

REF #CS012 4oz CS/12

LOT



For In Vitro Diagnostics Use

59°F (15°C)  86°F (30°C)



4300 Emperor Blvd - 400 Durham, NC 27703
Tel: 1-877-846-5393 Fax: 1-877-817-1716
www.cancerdiagnostics.com

Made in USA

Date Received: _____ Date Opened: _____

CoverSeal Plus™ is a mounting medium which enables (non-paraffin[®]) slide preparations to be simultaneously cleared and coverslipped in one easy step. This unique product eliminates the need to use xylene or xylene substitutes as a clearing agent. When using CoverSeal Plus™, simply do away with the final step of clearing and coverslip directly from 99% isopropyl alcohol. *Optimal medium for frozen sections and cytology applications.



DANGER **HAZARD STATEMENTS**

Highly flammable liquid and vapor. May be fatal if swallowed and enters airways. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. May cause respiratory irritation. May cause drowsiness or dizziness. Suspected of damaging fertility or the unborn child. May cause damage to organs through prolonged or repeated exposure.

PRECAUTIONARY STATEMENTS - PREVENTION

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe dust/fume/gas/mist/vapors. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves/protective clothing/eye protection/face protection.

PRECAUTIONARY STATEMENTS - RESPONSE

IF EXPOSED OR CONCERNED: call a doctor/get medical attention.

IF ON SKIN: Wash with plenty of water/shower. Take off all contaminated clothing and wash it before reuse. If skin irritation or rash occurs or persists: Get medical advice/attention.

IF INHALED: Remove person to fresh air and keep comfortable for breathing.

IF SWALLOWED: Immediately call a POISON CENTER/doctor/physician. Specific treatment (see first aid section on SDS). Do NOT induce vomiting.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

IN CASE OF FIRE: Use CO₂, dry chemical, or foam for extinction.

STORAGE & DISPOSAL

Keep container tightly closed. Store locked up in a well ventilated place at room temperature. Keep cool. Dispose of contents/container to an approved waste disposal plant.

NOTICE: Read Safety Data Sheet for additional information.

EMERGENCY CONTACT: Chemtec 1-800-424-9300



CoverSeal™ PLUS

Fast Drying Universal Mounting Medium

REF #CS001 500mL

LOT



For In Vitro Diagnostics Use

86°F (30°C)
59°F (15°C)

Date Received: _____ Date Opened: _____

CoverSeal Plus™ is a mounting medium which enables (non-paraffin®) slide preparations to be simultaneously cleared and coverslipped in one easy step. This unique product eliminates the need to use xylene or xylene substitutes as a clearing agent. When using CoverSeal Plus™, simply do away with the final step of clearing and coverslip directly from 99% isopropyl alcohol. *Optimal medium for frozen sections and cytology applications.



HAZARD **HAZARD STATEMENTS**

Highly flammable liquid and vapor. May be fatal if swallowed and enters airways. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. May cause respiratory irritation. May cause drowsiness or dizziness. Suspected of damaging fertility or the unborn child. May cause damage to organs through prolonged or repeated exposure.

PRECAUTIONARY STATEMENTS - PREVENTION

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe dust/fume/gas/mist/vapors. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves/protective clothing/eye protection/face protection.

PRECAUTIONARY STATEMENTS - RESPONSE

IF EXPOSED OR CONCERNED: call a doctor/get medical attention.

IF ON SKIN: Wash with plenty of water/shower. Take off all contaminated clothing and wash it before reuse. If skin irritation or rash occurs or persists: Get medical advice/attention.

IF INHALED: Remove person to fresh air and keep comfortable for breathing.

IF SWALLOWED: Immediately call a POISON CENTER/doctor/physician. Specific treatment (see first aid section on SDS). Do NOT induce vomiting.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

IN CASE OF FIRE: Use CO₂, dry chemical, or foam for extinction.

STORAGE & DISPOSAL

Keep container tightly closed. Store locked up in a well ventilated place at room temperature. Keep cool. Dispose of contents/container to an approved waste disposal plant.

NOTICE: Read Safety Data Sheet for additional information.

EMERGENCY CONTACT: Chemtrec 1-800-424-9300



4300 Emperor Blvd - 400 Durham, NC 27703

Tel: 1-877-846-5393 Fax: 1-877-817-1716

www.cancerdiagnostics.com **Made in USA**

PK1643 CoverSeal Plus 500mL, AVY-6042004 Rev. B 2021-03-02



CoverSeal™ PLUS

Fast Drying Universal Mounting Medium

REF #CS004 500mL CS/4

LOT



For In Vitro Diagnostics Use

86°F (30°C)
59°F (15°C)

Date Received: _____ Date Opened: _____

CoverSeal Plus™ is a mounting medium which enables (non-paraffin®) slide preparations to be simultaneously cleared and coverslipped in one easy step. This unique product eliminates the need to use xylene or xylene substitutes as a clearing agent. When using CoverSeal Plus™, simply do away with the final step of clearing and coverslip directly from 99% isopropyl alcohol. *Optimal medium for frozen sections and cytology applications.



DANGER **HAZARD STATEMENTS**

Highly flammable liquid and vapor. May be fatal if swallowed and enters airways. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. May cause respiratory irritation. May cause drowsiness or dizziness. Suspected of damaging fertility or the unborn child. May cause damage to organs through prolonged or repeated exposure.

PRECAUTIONARY STATEMENTS - PREVENTION

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe dust/fume/gas/mist/vapors. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves/protective clothing/eye protection/face protection.

PRECAUTIONARY STATEMENTS - RESPONSE

If EXPOSED OR CONCERNED: call a doctor/get medical attention.

IF ON SKIN: Wash with plenty of water/shower. Take off all contaminated clothing and wash it before reuse. If skin irritation or rash occurs or persists: Get medical advice/attention.

IF INHALED: Remove person to fresh air and keep comfortable for breathing.

IF SWALLOWED: Immediately call a POISON CENTER/doctor/physician. Specific treatment (see first aid section on SDS). Do NOT induce vomiting.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

IN CASE OF FIRE: Use CO₂, dry chemical, or foam for extinction.

STORAGE & DISPOSAL

Keep container tightly closed. Store locked up in a well ventilated place at room temperature. Keep cool. Dispose of contents/container to an approved waste disposal plant.

NOTICE: Read Safety Data Sheet for additional information.

EMERGENCY CONTACT: Chemtrec 1-800-424-9300



4300 Emperor Blvd - 400 Durham, NC 27703
Tel: 1-877-846-5393 Fax: 1-877-817-1716
www.cancerdiagnostics.com **Made in USA**

PK1644 CoverSeal Plus 500ml, Case of 4 AVY-6042005 Rev.B 2021-03-02